



RECOMANDARE

In legatura cu participarea **S.C.ELECTROSERVICE RB S.R.L. BUCURESTI**, la diverse licitatii publice, ca urmare a colaborarii si derularii mai multor contracte de furnizare, suntem in masura de a face cunoscute urmatoarele:

SE Pitesti a derulat cu **S.C.ELECTROSERVICE RB S.R.L. BUCURESTI** urmatoarele contracte:

Nr. Crt.	Denumirea lucrarii	Contract nr./data	Data inceperii lucrarii	Data terminarii lucrarilor	Observatii
1	Racc-Turbina cu abur nr.4-50MW :- Masuratori si vibratii pt.stabilirea cauzelor si a tehnologiilor de remediere a defectiunilor ;-turnare compozitie la cota de ebos lagar radial nr.2-TA4	16/26.04.2001	26.04.2001	15.06.2001	-
2	RC-Turbina nr.2-12MW- CET Sud I	12/11.02.2000	11.02.2000	28.04.2000	
3	RK-Turbina nr.3 CKTR-12MW – CET SudI-repaletare rotor	12/15.04.1999	19.04.1999	15.08.1999	
4	Racc-Turbina nr.4-50mw	16/07.04.1998	10.04.1998	31.07.1998	
5	Rebobinare stator pompa-EPA nr.3- CET Gavana	10/22.01.2002	22.01.2002	10.02.2002	
6	Rebobinare stator pompa termoficare-CET Gavana	384/14.02.2002	16.02.2002	In derulare	

Apreciem calificativul lucrarilor executate, din punct de vedere al calitatii, ca fiind:

Nr.crt	Denumirea lucrarii	Foarte bun	Bun	Satisfactor	Nesatisfactor
1	Racc-Turbina cu abur nr.4-50MW :- Masuratori si vibratii pt.stabilirea cauzelor si a tehnologiilor de remediere a defectiunilor ;- turnare compozitie la cota de ebos lagar radial nr.2-TA4	*			
2	RC-Turbina nr.2-12MW- CET Sud I	*			
3	RK-Turbina nr.3 CKTR-12MW –CET SudI- repaletare rotor	*			
4	Racc-Turbina nr.4-50mw	*			
5	Rebobinare stator pompa-EPA nr.3-CET Gavana	*			
6	Rebobinare stator pompa termoficare-CET Gavana				

In cursul derularii contractului au fost inregistrate neconformitati care au condus la refaceri partiale sau totale de produse : nu a fost cazul

Caz de accident tehnic produs din vina exclusiva a contractantului, datorita incalcarii normelor tehnice si a legislatiei in vigoare privind calitatea produselor : nu a fost cazul

Receptii amanate datorita nerespectarii parametrilor de calitate la terminarea lucrarilor si/sau la receptia finala : nu a fost cazul

Receptii respinse datorita nerespectarii parametrilor de calitate la terminarea lucrarilor si/sau la receptia finala : nu a fost cazul

Alte precizari : nu este cazul

Prezentul document are caracter de recomandare si este eliberat pe baza datelor inregistrate in cadrul unitatii noastre.

DIRECTOR
ING. IULIAN RICHITEANU





Translation from Romanian

**RECOMMENDATIONS REGARDING THE QUALITY OF THE PERFORMED WORKS
BENEFICIARY OF WORK**

S.E. PITESTI, KM 8 PETROCHIMISTILOR BLVD., PHONE: 048/218040

(Stamp of CONEL – S.C. Termoelectrica S.A. S.E. PITESTI

No. 1838, Date: 21.02.2002)

LETTER OF RECOMMENDATION

Regarding the participation of **S.C. ELECTROSERVICE RB S.R.L. BUCURESTI** in the different public auctions, on the basis of the collaboration and execution of several supply contracts, we can make known the following:

For SE Pitesti, **S.C. ELECTROSERVICE RB S.R.L. BUCURESTI** executed the following contracts:

Current no.	Name of work	Contract no./date	Date of commencing the work	Date of work completion	Remarks
1	Repairing of the steam turbine no. 4 – 50MW: Measurements and vibratic for establishing the causes and technologies of removing the defects composition casting at the quote of radial bearing rough work no. 2 – TA	16/26.04.200	26.04.200	15.06.200	
2	Overhauling of the turbine no.2 – 12 MW – CET Sud I	12/11.02.200	11.02.200	28.04.200	
3	Overhauling of the CKTR turbine no. – 12MW – CET Sud I – reblading of the rotor	12/15.04.199	19.04.199	15.08.199	
4	Repairing of the turbine no. 4 – 50 mw	16/07.04.199	10.04.199	31.07.199	
5	Rewinding of the pump stator– EPA no. 3 – CET Gavana	10/22.01.200	22.01.200	10.02.200	
6	Rewinding the central heating pump stator – CET Gavana	384/14.02.20	16.02.200	Ongoing	

We consider the quality of the performed works as follows:

Current no.	Name of work	Very good	Good	Satisfactory	Unsatisfactory
1	Repairing of the steam turbine no. 4 – 50MW: Measurements and vibratic for establishing the causes and technologies of removing the defects composition casting at the quote of radial bearing rough work no. 2 – TA	*			



2	Overhauling of the turbine no.2 – 12 MW – CET Sud I	*			
3	Overhauling of the CKTR turbine no. – 12MW – CET Sud I – reblading of the rotor	*			
4	Repairing of the turbine no. 4 – 50 mw	*			
5	Rewinding of the pump stator– EPA no. 3 – CET Gavana	*			
6	Rewinding the central heating pump stator – CET Gavana				

During the execution of the contract, there were encountered non-compliances which led to partial or total product renewal: it was not the case.

Technical accident only out of the fault of the contractor, due to non-complying with the technical norms and the law in force regarding the quality of products: it was not the case.

Delayed acceptances due to non-complying with the quality parameters upon the completion of works and/or final acceptance: it was not the case.

Rejected acceptances due to non-complying with the quality parameters upon the completion of works and/or final acceptance: it was not the case.

Other remarks: it is not the case.

This document is a recommendation and is issued on the basis of the data recorded by our company.

MANAGER
ENG. IULIAN RICHITEANU
(Signature: illegible)



S.C. Termoelectrica S.A.

Sucursala Electrocentrale București
CET București Sud

Nr. / 486 / 01.03.2002 /

RECOMANDARE

În perioada mai 1999 – prezent, S.C. ELECTROSERVICE R.B. S.R.L. București, a efectuat, ca subcontractor al S.C. SOCET S.A. București și ALSTOM POWER lucrări de reabilitare și reparații la turbinele VT 100 MW ale unităților 3 și 4 CET București Sud. Lucrările realizate au fost de bună calitate, demonstrând profesionalism, bună organizare și eficiență.

Unitatea nr. 3 a fost pusă în funcțiune și în prezent se află în probe de performanță. Nu există obiecțiuni la funcționarea turbinei.

Unitatea nr. 4 se află în stadiul de montaj, după ce au fost finalizate reparațiile și înlocuirile de piese, punerea în funcțiune fiind prevăzută în primăvara acestui an.

Până în prezent toate lucrările predate au fost de bună calitate.

S.C. TERMoeLECTRICA S.A.
SUCURSALE
ELECTROCENTRALE
BUCUREȘTI
CET. 3-4
DIRECTOR,
Ing. Dan POPESCU
